

FIELD INSPECTION REPORT

Date of Inspection: 22.12.2020	District: Sheikhpura
Name of the Road: Chorabari Simana Pul Se Pipari Palkhar Sarmana Pul	9.942 km
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	

1. Pavement		
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3. Road Furniture		
a)	Whether sign boards/illumination/roadside board/kit & 200m stones/Pavement road markings are provided and maintained.	Yes/No
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	


 (Signature) 22.12.2020

NAME: PANKAJ KUMAR
 DESIGNATION: JE, ARIYARI

Grasses in flank
 Head wall of HP
 is Broken

No 200M Stone
 & Road Furniture