


FIELD INSPECTION REPORT

Date of Inspection: - 22.12.20		District: - Kishanganj	
Division: - Kishanganj-I		Length(km): 1.448	
Name of the Road: Miraulung PWD road to Mahatab Tola via Najam Tola yadav Tola			
Scheme/Programme: MMGSY			
Package No.: N.A		Road Id No.: 21205813005	
Status of the Project:		Ongoing/Completed /Under Maintenance	
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
Sl. No	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction Condition	✓S/U	
b)	Condition of Surfacing	S/U✓	
c)	Riding Quality	S/U✓	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No✓	
f)	Contraction Joints Provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank / slope & raincuts if any	Yes/No✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting	✓S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges	✓S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-U-

NAME: - Er Radhesyam prajapati
J.E, R.W.D, Bahadurganj - I


 22.12.20
 J.E
 R.W.D (W) Division
 Kishanganj-1