

FIELD INSPECTION REPORT

Date of Inspection : 22.12.20	District: Gaya
Division : Gaya	Length (km): 1.384
Name of the Road: Gaya - Fatehpur Road to Bahera	
Scheme/Programme: MAINTENANCE	PM G 14
Package No.: BR-12R-708	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Under Maintenance
Work is a case of: New Connectivity/Up gradation/ Maintenance	New Connectivity

Sl/ No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Harishankar
NAME: J. E.

Plank
22.12.20
(Signature)