

FIELD INSPECTION REPORT

Date of Inspection : 22-12-2020		District: Subrah	
Division : Viper		Length (km): 1.980	
Name of the Road: House of Singh, 1 mela to house of Rajendra mela			
Scheme/Programme: MAINTENANCE		Road Id No.: 21005018021	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	
c)	Condition of railings/slab/approach for Bridges	S/SR/U	
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4. Compliance History			
a)	Status of ATR's & any others	-	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SR)	SRS
Unsatisfactory (U)	-

(Signature)

NAME: Dhanyaj Kumar
 DESIGNATION: J.E, R.W.D. Vairpur
 (Basantpur)