FIELD INSPECTION REPORT

Date of Inspection: 23.12.2020			District: Kishanganj		
Division: Kishanganj-1			Length(km): 1.16 上M		
Name o	of the Road:	dattak para +	TO PMUSY Road		
Scheme	e/Programme:	GTSNY			
Packag	e No.:	•	Road Id No.: 2120 58 18023		
Status	of the Project:	Ongoing/Completed /Under Maintenance			
Work is a case of:		New Connectivity/ Up gradation / Maintenance			
S1. No	Parameters to be checked			Remarks	
1.	Pavement			<i>J</i> 8/U	
a)	Road Junction Condition			√S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates			Yes/No	
	in case of CC Pavement.				
f)	Contraction Joints Provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank / shop & raincuts if any			Yes/No.	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			√S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			√S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			√\$/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m				
	stones/Pavemer	nt road markings	are provided and maintained		
4.	Compliance History				
a)	Status of ATR's & any others			MO	

Overall Rating:

Satisfactory(S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: Umesh Kumar Singh J.E, RWD, Kishanganj