

# FIELD INSPECTION REPORT

Date of Inspection:	22-12-2020	District:	Sheikhpura
Division:	Sheikhpura	Length (km):	1.440 km
Name of the Road:	Sasbahna Moushahi Tola Sozila Simana Bahura		
Scheme/Programme:	MAINTENANCE		
Admission No.:	Road ID No.:		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Expansion Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & ramps if any	✓ S/U	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m signs Pavement markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Gully in flank

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	✓
Unsatisfactory (U)	

(Signature)

NAME: PANDASKUMAR

DESIGNATION: JE, ARIYARI