FIELD INSPECTION REPORT

Date of Inspection: 23.12.2020			District: Kishanganj		
Division: Kishanganj-1			Length(km): 0.500 Km		
Name o	of the Road:	MUSY to	Sandha		
Scheme	e/Programme:	GTSNY			
Packag	e No.:		Road Id No.: 21205801895		
Status of the Project:		Ongoing/Completed /Under Maintenance			
Work is a case of:		New Connectivity/ Up gradation / Maintenance			
S1. No	Parameters to be checked		Remarks		
1.	Pavement /S/			√S/U	
a)	Road Junction Condition			√S/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			√\$/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints Provided or not (CC Pavement)			√Yes/No	
g)	Compaction of flank / shop & raincuts if any			/Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			IJS/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			-∕S∕/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			ا/SRI/ <i>گ</i>	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others			No	

Overall Rating:

Satisfactory(S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature)

NAME: Umesh Kumar Singh J.E, RWD, Kishanganj