

FIELD INSPECTION REPORT

Date of Inspection:	22.12.2020	District:	Samastipur
Division:	RWD Dalsinghsarai	Length(km):	1.030 Km.
Name of Road :	h048 to Parbhatola		
Scheme / Programme:	MAINTENANCE MGSY (Gen)		
Package No:	Road Id No:		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/ Up gradation/ Maintenance		
Sl. No	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction Condition	S	
b)	Condition of Surfacing	S	
c)	Riding Quality	S	
d)	Road Camber	S	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S	
f)	Constraction Joint provided or not(CC Pavement)	S	
g)	Compaction of flank/slope & raincuts if any	S	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S	
c)	Condition of railings/slab/approach for Bridge	S	
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S	
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	S.
Unsatisfactory(U)	

NAME: Ben Chandras Gupta
 DESIGNATION: Asst Engineer
 Working.

22/12/20
 (Signature)