

FIELD INSPECTION REPORT

Date of Inspection : 02.12.20		District: Gaya	
Division : Gaya		Length (km): 1.50	
Name of the Road: Meyari Road to Chini			
Scheme/Programme: MAINTENANCE		New Maintenance Policy 2018	
Package No.: MR-N/19-20/Gay/107		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		Completed	
Work is a case of: New Connectivity/Up gradation/ Maintenance		Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		S/U
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)		✓Yes/No N/A
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		✓S/SR/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SR/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U N/A
c)	Condition of railings/slab/approach for Bridges		S/SR/U N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Hein Shankar

Hein

NAME:

Hein
02.12.20
(Signature) T.E.