

FIELD INSPECTION REPORT

Date of Inspection : 23-12-2020		District: Gaya	
Division : Gaya		Length (km): 2.70 km	
Name of the Road: Bhadeji Borewag Road Tarnaxatal			
Scheme/Programme: MAINTENANCE		New Maint Policy 2018	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A	
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No	
Condition of Head Walls			
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SR/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U N/A	
c)	Condition of railings/slab/approach for Bridges	S/SR/U N/A	
Status of ATR's & any others			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
b)	Status of ATR's & any others	NA	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

R. K. Singh
(Signature)

NAME: Chandra Shekhar Kumar