	FIELD INSPECTION REPORT		
Date o	f Inspection: 23/12/2020 District: Madh	obuna	٦
Length (km): 3,21			
	of the Road: Surgigary - Kausihar		
	e/Programme: MAINTENANCE		
Packag		702015	
	Ongoing/Completed/Under Maintenance		
Sl. No.	Two Connectivity/Op gradation/ Maintenance		1
	Tarameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality		
d)	Road Camber	S/U	
S 1 2 2 2		S/U	
e)	Whether free from defects such as visible cracks, expaggregates in case of CC Pavement.	osed Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	tosedone
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage	500710	4
a)	Condition of head walls in Hume pipe culverts including its pair	ating S/SRI/U_	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A.	
c)	Condition of railings/slab/approach for Bridges	S/SRI/FI	
3.	Road Furniture	S/SRI/U-	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/No		to be done
4	Compliance History		Thompton b
a)	Status of ATR's & any others		
Warell D	otin-		
verall R	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI	<u></u>	
	Unsatisfactory (II)	)	

Cation (C)	
Satisfactory (S)	C
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

SDBC work has been done in most of the length of the mad. The work (DBC in about 250 m length is in progress which is to complete imperso. Other works are yet to be done. (Signature)

NAME:

SANJEEV FUMAR

DESIGNATION:

EAGOUNE ENVINDER CE-30/1, Puro, Patra