

# FIELD INSPECTION REPORT

Date of Inspection : 19-12-2020	District: Sitamarhi
Division : Belsond	Length (km): 8
Name of the Road: Kuahi to gidhhg road	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 316080008029
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U✓
b)	Condition of Surfacing	S/U✓
c)	Riding Quality	S/U✓
d)	Road Camber	S/U✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No✓
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U✓
c)	Condition of railings/slab/approach for Bridges	S/SRI/U✓
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME:

DESIGNATION:

LALIT PRAKASH  
E.E.

Lalitha Prasad  
(Signature)