

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020		District: West Champaran	
Division : R&D Works Div. Bagaha		Length (km): 4.1 KM	
Name of the Road: Khatia Bhaube Jike gharkhe Pass nonitola		Scheme/Programme: MAINTENANCE hole true malch toli hoker to PWD sadak Tak	
Package No.: RM/WE/MS/19/003		Road Id No.: 31809101002	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance - New Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

C.C. Pavement is not provided

Overall Rating :

Satisfactory (S)	—	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

21/21
23.12.2020
(Signature)

NAME: Rathesh Paswan
DESIGNATION: Executive Engineer