FIELD INSPECTION REPORT

Date of	Inspection: 3	1 11 Carol District	Norah	100
Division			<u> </u>	
	V-04 - N	mkpin pagetaflength (km): 1-97 Km		
	Programme:	MAINTENANCE SEMANIJA		
		= 13A4 119 - 00 2 Road Id No.: 3 3 180 9	120007	
Status o	f the Project:	Ongoing/Completed/Under Maintenance	1120-9	
and the state of t	a case of:	New Connectivity/Up gradation/ Maintenance _ ~	w martitan	,a.Y
SI. No.			Remarks	
1.	Pavement			
a)	Road Junction	S		
b)	Condition of S	2	7	
c)	Riding Quality	S	7.	
d)	Road Camber	S	SWENING .	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			C. Parkerni
ŋ	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			ڹٛ
2.	Cross Drains	ge		
a)	Condition of head walls in Hume pipe culverts including its painting		S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			14
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furnitu	re		
a)	Whether sign stones/Paveme	boards/informatory/cautionary Board/km & 200m nt road markings are provided and maintained —	yes	
4.	Compliance H	istory		
a)	Status of ATR'	s & any others		

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Rathesh Paswar.

DESIGNATION: Executive Engineer