## FIELD INSPECTION REPORT

		3. (2.2020 District: arest cham	
Divisio	#: K.M.D. M	KSDIV-BOSKOS Longth (km): 1-840 km	DETAN
Name (	of the Road: Kerrogramme:	cathali la Dans	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Packag	e No.: 0 Pullan	MAINTENANCE	
Status	of the Project:	Ongoing/Completed/Under Maintenance	2012
ALM AND THE RESIDENCE	s a case of:	New Connectivity/Up gradation/ Maintenance _ N4	
SI. No.		Parameters to be checked	W Mon
1.	Pavement		
a)	Road Junction condition		
b)			
		Condition of Surfacing	
c)	Riding Quality		2
d)	Road Camber		<
e)	Whether fre aggregates in	e from defects such as visible cracks, exposed case of CC Pavement.	
ŋ	Contraction Joints provided or not (CC Pavement)		<del></del>
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drain	age	yes -
a)	Condition of	S	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		yes
4.	Compliance H	listory	1
a)	Status of ATR	's & any others _ NO	to".

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	5
Unsatisfactory (U)	

(Signature)

NAME: Richneck POOW OUR.

DESIGNATION: - EXECUTIVE ENGINEER