

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020		District: West Champaran	
Division : RWD Works Dir Beghalpur		Length (km): 4.2 KM	
Name of the Road: Samserna to Khatuhawa			
Scheme/Programme: MAINTENANCE			
Package No.: R/M/WG/BAG/19-003		Road Id No.: 31809102036	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of:		New Connectivity/Up gradation/ Maintenance - New maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	—
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	—	S
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME: Ratnesk Paswan
DESIGNATION: Executive Engineer

23/12/20
(Signature)

is not provided