

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020		District: Nalanda	
Division : Hilla		Length (km): 1.6 Km	
Name of the Road: Hilla Islampur PWD road to Bhagwanpur Village Tak			
Scheme/Programme: MAINTENANCE		MR-3054	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U S
b)	Condition of Surfacing		✓S/U S
c)	Riding Quality		✓S/U S
d)	Road Camber		✓S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		✓Yes/No/Yes
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U N.A
c)	Condition of railings/slab/approach for Bridges		S/SRI/U N.A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓Yes/No ^{Yes}
4.	Compliance History		
a)	Status of ATR's & any others		—

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


23.12.2020
(Signature)

NAME: Rana Barun Kumar Singh

DESIGNATION: Executive Engineer.