

FIELD INSPECTION REPORT

Date of Inspection : 25/12/2020		District: Madhupur
Division : Madhupur		Length (km): 6.40
Name of the Road: Bhalwa to Ghailad		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.: 21004300076
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	B/U
b)	Condition of Surfacing	B/U
c)	Riding Quality	B/U
d)	Road Camber	B/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Remarks: Road is in poor condition. Need to be repaired.

Remarks: Road is in poor condition.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

The agency has not started the work. Few potholes are to be repaired. C&P should be sealed to save the upper surface.

Wan
25/12/2020
(Signature)

NAME: SANJEEV KUMAR

DESIGNATION: EXECUTIVE ENGINEER
CE-3 (B); RWD, Patna