

FIELD INSPECTION REPORT

Date of Inspection : 22/04/2020	District : Road Deptt
Division : Road Deptt	Length (km) : 3.00
Name of the Road : NH 10 Chudhwa to Gull, Khandwa	
Scheme/Programme : MAINTENANCE	
Package No.1	Road Id No. 21004305078
Status of the Project : Ongoing/Completed/Under Maintenance	
Work is a case of : New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U <i>few pot-patches are to be repaired.</i>
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

few pot-patches are to be repaired. The agency has started the work.

Wan
22/04/2020
(Signature)

NAME: SANJEEV KUMAR
DESIGNATION: EXECUTIVE ENGINEER
CE-3 Up, RWD, Bafra