

FIELD INSPECTION REPORT

Date of Inspection : 24/11/2020	District: Madhepura
Division : Madhepura	Length (km): 2.60
Name of the Road: Madhepura Panni bank to Sahngarh	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 21004708079
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	U

The agency has not started the work. The road is in bad condition.

W/om 24/11/2020
(Signature)

NAME: SANJEEV KUMAR
DESIGNATION: EXECUTIVE ENGINEER
CE-3 off, PWD, Patna