FIELD INSPECTION REPORT

Date of 1	Inspection:	3.12.2090 Dis	triat	to all fulfillment and a company of the company of	
Division	: Sinc	and the second s	trict: Spwaw ingth (km): 6.00 km		
Name of		awallato Ramons	igth (km): 6.00 km.	As ASSE when the supplier and the suppli	
Scheme/	Programme:	MAINTENANCE .	and parpus		
Package		and the first time and interpretation of the second	ad Id No.:	Morphison angles (commerce and minimum) is a management and all analysis of granular and	
	f the Project:	Ongoing/Completed/Und			
Work is	a case of:	New Connectivity/Up gra	adation/ Maintenance	Mage field and the commencer and an administration of the commence of the comm	
Sl. No.		Parameters to be c	Made print, may be not a few of the second o	Remarks	
1.	Pavement				
a)	Road Junction condition			1	,
b)	Condition of Surfacing			S/U	
				SILLSon	e pot h
c)	Riding Quality			S/U	present.
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
1)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any				mula
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				7 A
c)	Condition of railings/slab/approach for Bridges				A .
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Yes/No	
4.	Compliance History				
a)	Status of ATR	s & any others		and a final of a season of the	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	The state of the s
Unsatisfactory (U)	U .

Ravesh Langan Pandey. Exembre Engineer. GelF-1.

(Signature)

NAME:

DESIGNATION: