FIELD INSPECTION REPORT

Date of 1	Inspection :	District: Sinan.			
Division: Sinan-1. Length (km): 5.50 km.					
Name of	the Road: 3	sharthui to	Saranje.	and a supplied to the control of the	
Scheme/	Programme:	MAINTENANCE		and the state of t	
Package No.:			Road Id No.:		
The second secon	f the Project:		ed/Under Maintenance	the state of the second state of the second state of the state of the second state of	
Work is	a case of:		/Up gradation/ Maintenance		
Sl. No.		Parameters t	o be checked	Remarks	
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/V are visible	
c)	Riding Quality			STU Poolion a	
d)	Road Camber			STU rectific	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No raine	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance History				
a)		's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SPT.
Unsatisfactory (U)	*

Lakeoh Ranjan Pandey.
Execulive Engineer.
% CE-1.

(Signature)

NAME:

DESIGNATION: