

FIELD INSPECTION REPORT

Date of Inspection : 23-12-2020		District: West Champaran
Division : WORK DIV - Bagaha-2		Length (km): 4.6 km
Name of the Road: Tamkuhwa to Ghewarahi		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance - M/R-3054	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	Pot developed in D.T. portion
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	
f)	Contraction Joints provided or not (CC Pavement)	p.c.c. rough surface
g)	Compaction of flank/slope & raincuts if any	Raincut in blank
2.	Cross Drainage	NO
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	SRT
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	11

pot patch work started

(Signature) 23-12-20

NAME: Ratnesk Paswan

DESIGNATION: Executive