

FIELD INSPECTION REPORT


Date of Inspection : 23.12.2020		District: MADHUBANI
Division : MADHUBANI		Length (km): 4.0 km
Name of the Road: JIWA CHH SE KAPLESWAR TALUK		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing except some stretches damaged in flood	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No YES/NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SR2
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U SR2
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NU
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR2
Unsatisfactory (U)	

Some stretches (small) damaged in flood, Reported in FDR.


(Signature)

NAME: K.R. RANJAN

DESIGNATION: EE