

FIELD INSPECTION REPORT

Date of Inspection : 23.12.2020		District: Ara	
Division : Ara		Length (km): 2.75 km	
Name of the Road: Khesariya village to Sopalpur			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U ✓	
b)	Condition of Surfacing	S/U ✓ (cc pavement)	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓	
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No ✓	
4.	Compliance History		
a)	Status of ATR's & any others	N/A	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

U

Remarks: Appearance of edge-breakage, patches & pots at some places. Exposed aggregates & cracks in cc pavement. Road furniture is incomplete.

NAME:

Rectification done or not : Not done
Rectification started or not : Not
Notice Issued or not : Not

(Signature)

23/12/20
EE

(N.A. ISHRAT)