

FIELD INSPECTION REPORT

DATE OF INSPECTION:	19/12/2020	DISTRICT:	Purnea						
DIVISION:	Bhambhala	LENGTH:	1.608 KM						
NAME OF THE ROAD:	Tol to Urano tola via gulaila shitta								
SCHEME/PROGRAMME:	MMBSY	MAINTENANCE							
PACKAGE No:		ROAD ID No.:							
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE								
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE								
SLNO	PARAMETERS TO BE CHECKED	REMARKS							
1	PAVEMENT								
A	ROAD JUNCTION CONDITION	'S'							
B	CONDITION TO SURFACING (B.T)	'SRI'							
C	RIDING QUALITY	'S'							
D	ROAD CAMBER	'S'							
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE OF CC PAVEMENT	'S'							
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	'S'							
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	'S'							
2	CROSS DRAINAGE								
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	'S'							
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N.A							
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A							
3	ROAD FURNITURE								
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	'S'							
4	COMPLIANCE HISTORY								
A	STATUS OF ATR's & ANY OTHERS	N.A							
OVERALL RATING	<table border="1"> <tr> <td>SATISFACTORY(S)</td> <td></td> </tr> <tr> <td>SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)</td> <td>'SRI'</td> </tr> <tr> <td>UNSATISFACTORY(U)</td> <td></td> </tr> </table>			SATISFACTORY(S)		SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	'SRI'	UNSATISFACTORY(U)	
SATISFACTORY(S)									
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	'SRI'								
UNSATISFACTORY(U)									

NAME: Surendra prasad Singh
DESIGNATION: Junior Engineer

Sd/-
19/12/2020
SIGNATURE