

FIELD INSPECTION REPORT

DATE OF INSPECTION:	19/12/2020	DISTRICT:	Purusa
DIVISION:	Dhamdaha	LENGTH:	3.395 KM
NAME OF THE ROAD:	Tos to Gulaila Nihal Tola		
SCHEME/PROGRAMME:	MMBSY (World Bank) MAINTENANCE		
PACKAGE No:	ROAD ID No.1		
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SLNO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	'S'	
B	CONDITION FO SURFACING	'S'	
C	RIDING QUALITY	'S'	
D	ROAD CAMBER	'S'	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	'S'	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	'S'	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	'S'	
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	'S'	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	'S'	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	N.A	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	'S'	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR's & ANY OTHERS	N.A	
OVERALL RATING	SATISFACTORY(S) SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI) UNSATISFACTORY(U)		

NAME: Surendra prasad Singh
DESIGNATION: Junior Engineer

S.P.Singh
19/12/2020
SIGNATURE