

FIELD INSPECTION REPORT

Date of Inspection : 20/12/2020 District: Araria
 Division : Araria Length (km): 2.360
 Name of the Road: PMGSY Hosur - also Bhadaina Mandal Tola, via Thahri
 Scheme/Programme: MAINTENANCE Tathbandh Tola
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

S. No.	Parameters to be checked	Remarks
Pavement		
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U / SRI
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	X

NAME: Kumar Geetan

DESIGNATION: AR

20/12/20
 Palan

Kumar
 20/12/20
 AR