FIELD INSPECTION REPORT

		District: SARAN			
Date of Inspection: 19.12.2021 Division: MARHAUAA		District Sen ViMI			
		Length (km): 3 . 890 K·M .			
Name of the Road: @@	Than Noum pr	ngs y part to Yakuch p masy.			
Scheme/Programme:	MAINTENANCE				
Package No.:		Road Id No.: 318045 17016			
Status of the Project:	Ongoing/Completed/Under Maintenance				
Work is a case of	New Connectivity/Up gradation/ Maintenance				
Sl. No.	Parameters	to be checked Remarks			

l. No.	Parameters to be checked,	Remarks
1.	Pavement	Hillians
a) -	Road Junction condition	SIU
b)	Condition of Surfacing	.8/U
c)	Riding Quality	~8/U
d)	Road Camber	87Ú
e) -	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/Noon
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/Ü
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Eurniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	NO

OverallRating

Satisfactory (S)		- 14 6		# S
Satisfactory but requ	ires Impro	vement	(SRI)	
Unsatisfactory (U)		and the second		

(Signature) 2020

NAME: Show Rom Roc

DESIGNATION: A.E.