

FIELD INSPECTION REPORT

Date of Inspection:	22/12/2020	District:	Darbhanga
Division:	Darbhanga-1	Length(Km):	
Name of Road:	PMGSY Murliya Sonki	path se chhawel a gaon tak path	
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/.Maintenance		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	No Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank /slope & raincuts if any	Yes/No No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N/A S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	N/A S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U N/A
3	Road Furniture	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ <u>Pavement road markings are provided and maintained</u>	Yes Yes/No
3	Compliance History	
a)	Status of ATR's & any others	

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	U

few point of road is damaged due to flood current of previous year.

(Signature)

Name:

Designation: