FIELD INSPECTION REPORT

		22-12-20	District: Machuban	,	
Division: Tanager Length (km):					
	f the Road:		o Khanna tol Ba	lan River	
	Programme:	MAINTENANCE			
Package			Road Id No.:		
Status of the Project: Ongoing/Completed/Under Maintenance					
Work is	a case of:	New Connectivity/Up gradation/ Maintenance			
Sl. No.	And the second s	Parameters to b	e checked	Remarks	
1.	Pavement				
a)	Road Junction condition			√s/U	
b)	Condition of Surfacing			\\$/ U	
c)	Riding Quality			S/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2,	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			'√S/SRI/U	
. c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furnitu	C1	Simple state of the state of th		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
	Compliance H	Story		garantani kanada k Baharan kanada kan	
a)	Status of ATR's & any others			110	

Overall Rating :

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: S.K. Jumen

DESIGNATION: 16