

FIELD INSPECTION REPORT

Date of Inspection : 21/12/20	District: Nalanda
Division : Rajgir	Length (km): 0.720 km.
Name of the Road: T024 Silow Bhu Road to Milkipur Road to Bhagwanpur Road in Rajgir Block.	
Scheme/Programme: MAINTENANCE	NABARD
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	S/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No (N/A)
f)	Contraction Joints provided or not (CC Pavement)	Yes/No (N/A)
g)	Compaction of flank/slope & raincuts if any	Yes/No (N/A)
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/✓/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U (N/A)
c)	Condition of railings/slab/approach for Bridges	S/SRI/U (N/A)
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/✓/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Ranabrewesh Kumar
SE
NAME: Rajgir


21/12/20
(Signature) SE.