

FIELD INSPECTION REPORT

Date of Inspection : 19.12.20		District: KAZMUR	
Division : Mohania		Length (km): 1.150 km.	
Name of the Road: L071 NH2 to Sarangpur (VR 67)			
Scheme/Programme: MAINTENANCE			
Package No.: BR05R-324		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance ☒			
Work is a case of: New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	✓Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	'S'
Unsatisfactory (U)	

NAME: Satyendra Prasad Lal

(Signature) Sunil
19/12/20