

|                        |                                            |              |           |
|------------------------|--------------------------------------------|--------------|-----------|
| Date of Inspection :   | 19.12.20                                   | District:    | K A S MUR |
| Division :             | Mohania                                    | Length (km): | 0.60 K.m. |
| Name of the Road:      | Lerma Samurni Road to Larne                |              |           |
| Scheme/Programme:      | MAINTENANCE                                | MMGSY (Gem)  |           |
| Package No.:           |                                            | Road Id No.: |           |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |           |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |           |

| Sl. No. | Parameters to be checked                                                                                        | Remarks       |
|---------|-----------------------------------------------------------------------------------------------------------------|---------------|
| 1.      | Pavement                                                                                                        |               |
| a)      | Road Junction condition                                                                                         | ✓ S/U         |
| b)      | Condition of Surfacing                                                                                          | ✓ S/U         |
| c)      | Riding Quality                                                                                                  | ✓ S/U         |
| d)      | Road Camber                                                                                                     | ✓ S/U         |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | Yes/No        |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | Yes/No        |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | Yes/No        |
| 2.      | Cross Drainage                                                                                                  |               |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | ✓ S/SRI/U     |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | S/SRI/U       |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | S/SRI/U       |
| 3.      | Road Furniture                                                                                                  |               |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m ✓ Yes/No |
| 4.      | Compliance History                                                                                              |               |
| a)      | Status of ATR's & any others                                                                                    | No            |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | (S) |
| Satisfactory but requires Improvement (SRI) |     |
| Unsatisfactory (U)                          |     |

NAME: Satyendra Basad Lal

(Signature) Satendra  
19/12/20  
S-Be