

FIELD INSPECTION REPORT

Date of Inspection : 23/12/20

Division : Rajgir

District : Nalanda

Name of the Road: Rajgir basuar Pakki Sadak se Bahai Suhaj Middle School Par Godam Anganwad i Hote Hue Mahadalit Samudait Bhawan Tak Sadak Nizman.

Length (km): 1.00 k.m.

Scheme/Programme: MAINTENANCE

Package No.:

MNP (4515)

Status of the Project:

Road Id No.:

Work is a case of:

Ongoing Completed Under Maintenance

New Connectivity/Up gradation. Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓
b)	Condition of Surfacing	S/✓
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Construction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained 200m	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

(N/A)
(N/A)

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Ramprewesh kumar
JE

NAME: Rajgir

23/12/20
(Signature) JE.