

FIELD INSPECTION REPORT

Date of Inspection :	18.12.2020	District:	Nalanda
Division :	Rajgir	Length (km):	1.00
Name of the Road:	bikar Enkya Road Me Lenin nagar 32.12 To 12.12.2020		
Scheme/Programme:	MAINTENANCE ✓		4515 M.31P
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	HA S/U
d)	Road Camber	HA S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4	Compliance History	
a)	Status of ATR's & any others	—

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

[Signature]
18/12/2020
(Signature)

NAME: SHIVAPRAKASH GUPTA
AE (BEN)