FIELD INSPECTION REPORT

	of Inspection :	27/17/20 1	istrict: madlulari	
	Tangth (low)			
	of the Road:	Bela to Panjas		
Schem	e/Programme:	MAINTENANCE	179 179 1	
Packag		Re	ond Id No.:	
	Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Un gradation/ Maintenance			
1344 540 1104	(A) topology i service memory and	New Connectivity/Up gr	adation/ Maintenance	
SI. No.		Parameters to be c	hecked	Remarks
1.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			NS/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Wes/No
f)	Contraction Joints provided or not (CC Pavement)			Xes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Euraniture		returning to the second se	
^ 1	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No/
	Compliance His	lory		the first of the second
a) S	Status of ATR's	& any others		NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: D. L. Jures DESIGNATION: 4&