## FIELD INSPECTION REPORT

Date of			`	and the second result in the second result is a second result.	
Date of Inspection: 23.12.2020  Division: 24.15.40466			District: Lawinforcy'		
an a sammada	KWD	akhifonai Li	ength (km):	3.461 Kr	1
	the Road: Pi	1687 Road	ength (km): ( 3 Lander	to Bagio	La Tola
Package	Programme:	WARNTENANCE (			
	the Project:		oad Id No.:	01 ac - 22	
	a case of:	Ongoing/Completed/Un			7.6
1.1 (26623N)	a case or.	New Connectivity/Up gr		enance	
Sl. No.		Parameters to be o	hecked		Remarks
1.	Pavement				
a)	Road Junction condition			<del>-8/U</del>	
b)	Condition of Surfacing			C\$#U	
c)	Riding Quality			⊸s/U	
d)	Road Camber			✓S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			¥es/No	
I)	Contraction Joints provided or not (CC Pavement)			¥cs/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			-8/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture			5,5,6,6	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance H	istory	1		
a)	Status of ATR'				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	0.0
Unsatisfactory (U)	SRI

23.12.70 JE 34 14 180 W

(Signature)

NAME:

DESIGNATION: