## FIELD INSPECTION REPORT

Date of	Inspection: 2	+ listro District:	District: Jamus		
Division	1: Jamil	Length	Length (km): 1Km		
Name o	f the Road: Be	idho Sharma House Via N	instit to shool ka	itha woni Ro	
	/Programme:	MAINTENANCE 4.T.S.	NY	***	
Packag	e No.:		No.: 208041018	332	
Status of the Project: Ongoing/Comp		Ongoing/Completed/Under Mo	leted/Under Maintenance		
Work is a case of: New Connec		New Connectivity/Up gradano	tivity/Up gradation/ Maintenance		
SINO		the religion of the streets		Remarks	
	Pavement				
a)	Road Junction condition			√8/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			√S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Yes/No			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Xes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
	are as to the	"程度"之代表。 第二章			
a)	Condition of head walls in Hume pipe culverts including its painting			s/spa/u	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			SISRIFU	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U H	
13.	e e contraction de la contract				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
神響	skenimilli trest	II in the second se	Annacidate possible		
a)	MANAGEMENT STATES	's & any others		H/A	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	5.R.I
Unsatisfactory (U)	

Aginas 10

(Signature)

NAME:

**DESIGNATION:**