FIELD INSPECTION REPORT

| Date of I | nspection: 2 | 41412 | District: Jamui | |
|-----------|--|---|--|------------------|
| Division: | | | Length (km): 0.700km | |
| Name of | the Road: w | mesh Vishwakan | na House TO Samudayik B! | wen REOTON |
| | Programme: | MAINTENANCE | 4.7.2.N.Y | |
| Package | No.: | | Road Id No.: 20804101 | 874 |
| Status of | f the Project: | Ongoing/Completed | /Under Maintenance | |
| | a case of: | New Connectivity/U | Jp gradation/ Maintenance | |
| SI No. | | Parameters to | be checked | Remarks |
| 1. | Pavement | | | |
| a) | Road Junction | ondition | | √ 8/U |
| b) | Condition of Surfacing | | | ✓S/U |
| c) | Riding Quality | | | √\$/U |
| d) | Road Camber | | | √8/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| 12 | Cross Drain | e i i i i i i i i i i i i i i i i i i i | | |
| a) | Condition of head walls in Hume pipe culverts including its painting S/SRI/ | | | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U-N |
| c) | Condition of railings/slab/approach for Bridges | | | -S/SRL/U N |
| 3 | Road Karnii | make a market | | |
| a) | | | /cautionary Board/km & 200m e provided and maintained | Yes/No |
| 4. | Compliance | filiory 7 | | 2000年6月 1年20日 |
| a) | Status of AT | R's & any others | | |

Overall Rating

| Satisfactory (S) | |
|---|--------|
| Satisfactory but requires Improvement (SRI) | 5. R.L |
| Unsatisfactory (U) | |

Janar 24-12-20

(Signature)

NAME:

DESIGNATION: