

FIELD INSPECTION REPORT

Date of Inspection : 17-12-2020 District: Banka
 Division : Banka-1 Length (km):
 Name of the Road: Katchi Mase Patna PMGSY Road (Kot haza) to Kuamgaon
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.: 1.483
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a.	Road Junction condition	✓
b.	Condition of Surfacing	✓SU
c.	Riding Quality	✓SU
d.	Road Camber	✓SU
e.	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓SU
f.	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g.	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a.	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b.	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c.	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a.	Whether sign boards/informatory/cautionary Board 10m & 200m cones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a.	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	SRI

NAME: Ashok Kumar Sinha
 Junior Engineer

Prin
 17/12/2020
 (Signature)