	FIELD INSPECTION REPORT	il all this Management to the fact the second second
DATE OF INSPECTION:	18/12/2020 DISTRICTI Pusnea Dhamdaha LENGTH 0,600 KM	
DIVISION:	Dhamdaha IENOTIII 0,600 KM	
NAME OF THE ROAD:	LO32 to Baruna Tola	
SCHEME/PROGRAMME:	MM G/SY MAINTENANCE	
PACKAGE No:	ROAD ID No.1	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SL.NO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
A	ROAD JUNCTION CONDITION	`S'
В	CONDITION FO SURFACING	3'
С	RIDING QUALITY	<u>'3'</u>
D	ROAD CAMBER	`3'
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	`S'
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	<u>'S'</u>
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	31
2	CROSS DRAINAGE	
A 18 3 5 5	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	N.A
<u> </u>	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	N. 4
C 3.4	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	<u> </u>
3	ROAD FURNITURE	
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	<i>'3'</i>
4	COMPLIANCE HISTORY	
A	STATUS OF ATR'S & ANY OTHERS	N.A
OVERALL RATING	1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	Sego
DAEUWIT UVILLIA	SATISFACTORY(S)	(3)
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	17.5
	UNSATISFACTORY(U)	

Kymouz Crewsar

NAME: DESIGNATION: