

# FIELD INSPECTION REPORT

Date of Inspection: 02/12/20 District: Bonga  
 Division: Bonga-1 Length (km): 11.27  
 Name of the Road: Ajit Nagar to Bindli Shankarpur RCD Road  
 Scheme/Programme: MAINTENANCE  
 Package No.: Road Id No.:  
 Status of the Project: Ongoing/Completed/Under Maintenance  
 Work is a case of: New Connectivity/Up gradation/ Maintenance

| Sl. No.   | Parameters to be checked                                                                                            | Remarks     |
|-----------|---------------------------------------------------------------------------------------------------------------------|-------------|
| <b>1.</b> | <b>Pavement</b>                                                                                                     |             |
| a)        | Road function condition                                                                                             | ✓SU         |
| b)        | Condition of Surfacing                                                                                              | ✓SU         |
| c)        | Riding Quality                                                                                                      | ✓SU         |
| d)        | Road Camber                                                                                                         | ✓SU         |
| e)        | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement                         | Yes/No N.A. |
| f)        | Contraction Joints provided or not (CC Pavement)                                                                    | Yes/No N.A. |
| g)        | Compaction of Blank/slope & raincuts if any                                                                         | Yes/No ✓    |
| <b>2.</b> | <b>Cross Drainage</b>                                                                                               |             |
| a)        | Condition of head walls in Hume pipe culverts including its painting                                                | ✓SRM        |
| b)        | Condition of Abutment & Wing walls, Slab in RCC culverts                                                            | ✓SRM N.A.   |
| c)        | Condition of railings/slab/approach for Bridges                                                                     | ✓SRM N.A.   |
| <b>3.</b> | <b>Road Furniture</b>                                                                                               |             |
| a)        | Whether sign boards/informatory/cautionary Road km & 200m stones/Pavement road markings are provided and maintained | ✓Yes/No     |
| <b>4.</b> | <b>Compliance History</b>                                                                                           |             |
| a)        | Status of ATR & any others                                                                                          |             |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRM)

Unsatisfactory (U)

Unsatisfactory

*Bhishu*  
24/12/2020

(Signature)

NAME: Ashok Kumar Singh  
 Junior Engineer