

FIELD INSPECTION REPORT

Date of Inspection : _____ District: Siwan
 Division : Siwan-1 Length (km): 1.20 Km
 Name of the Road: Jatawana more to belwar
 Scheme/Programme: MAINTENANCE
 Package No.: _____ Road Id No.: _____
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: Need Connectivity Up gradation Maintenance (3054)

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	करमदीश आजा है। (L.O.A निम्न हो जाये)
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks exposed aggregates in case of C.C. Pavement	Yes/No
f)	Continuation joints provided or not (C.C. Pavement)	Yes/No
g)	Compaction of Bank slope & rain gutters	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Flume pipe culverts including its painting	S/SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI
c)	Condition of railings slab approach for Bridges	S/SRI
3.	Road Furniture	
a)	Whether sign boards-informatory cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NAME:

(Signature)

(Signature)

24.12.2017
 H.B. Siwan Sarker