

FIELD INSPECTION REPORT

Date of Inspection : _____ District: Siwam
 Division : Siwam-1 Length (km): 1.600 km
 Name of the Road: Chandpur to Mehadan
 Scheme/Programme: MAINTENANCE MR 3059
 Package No.: _____ Road Id No.: _____
 Status of the Project: Completed Under Maintenance
 Work is a case of: New Existing Extension Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Functionality	S-I
b)	Condition of Surface	S-I
c)	Road Quality	S-I
d)	Road Camber	S-I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of C/Pavement	Yes/No
f)	Condition of drainage in case of C/Pavement	Yes/No
g)	Condition of the road surface	Yes/No
2.	Cross Drainage	
a)	Condition of head wall in Drainage pipe culverts including its painting	S/SRI/I
b)	Condition of Abutment & Wing walls, Slope in RCC culverts	S/SRI/I
c)	Condition of culverts with approach for Bridges	S/SRI/I
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of A/R's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Ravi
29/12/2020
JE
 (Signature)

NAME: Ravindra Kumar Mondal
Junior Engineer

काशी प्रदेश नदी निकाश
 (L.O.A. निगम)
 नदी क्लाइड