

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Banka</u>
Division : <u>Banka-I</u>	Length (km): <u>0.726 km</u>
Name of the Road: <u>Shambhuganj Dalwa Road to Chautara</u>	
Scheme/Programme: <u>MAINTENANCE</u>	
Package No.:	Road Id No.: <u>0-726 km</u>
Status of the Project:	Ongoing/Completed/Under Maintenance <u>out of maintenance</u>
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U <u>N/A</u>
b)	Condition of Surfacing	S/U <u>N/A</u>
c)	Riding Quality	S/U <u>N/A</u>
d)	Road Camber	S/U <u>N/A</u>
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No <u>N/A</u>
f)	Contraction Joints provided or not (CC Pavement)	Yes/No <u>N/A</u>
g)	Compaction of flank/slope & raincuts if any	Yes/No <u>N/A</u>
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <u>-</u>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <u>-</u>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <u>-</u>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No <u>-</u>
4.	Compliance History	
a)	Status of ATR's & any others	<u>-</u>

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Kumar Jaiswal

(Signature)

NAME: