

FIELD INSPECTION REPORT

Date of Inspection : 12.09.2020 District: Siwan
 Division : Siwan-I Length (km):
 Name of the Road: Sanyampur to Dhanaut
 Scheme/Programme: MAINTENANCE
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance ✓ MR-3054
 Work is a case of: New/Rehabilitation/Regular Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surface	SIU ✓
c)	Riding Quality	✓ SIU
d)	Road Camber	SIU ✓ YES/NO
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	YES/NO ✓
f)	Contraction joints provided or not (CC Pavement)	✓ YES/NO
g)	Compaction of flanker & shoulders	✓ YES/NO
2.	Cross Drainage	
a)	Condition of head wall in Dune pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings & approach for Bridges	✓ S-SRI-U
3.	Road Furniture	
a)	Whether sign boards-informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ YES/NO
4.	Compliance History	
a)	Status of ATR's & any others	NO ATR

Overall Rating :
 Satisfactory (S)
 Satisfactory but requires Improvement (SRI)
 Unsatisfactory (U) ✓

NAME:

(Signature)
 94.12.2020
 A.E.