

FIELD INSPECTION REPORT

Date of Inspection :	District: <u>Siwan</u>
Division: <u>Siwan-1</u>	Length (km): <u>1.60 KM</u>
Name of the Road: <u>Bhindi Joda to Nirmal Nagar</u>	
Scheme/Programme: <u>MAINTENANCE</u>	<u>MR-3054</u>
Package No.:	Road Id No.:
Status of the Project: <u>Ongoing/Completed/Idle Maintenance</u>	
Work is a case of <u>New Construction/Upgradation/Maintenance</u>	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/I
b)	Condition of Surfacing	S/I
c)	Riding Quality	S/I
d)	Road Camber	S/I
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
	Condition of the provided outer of CC Pavement	Yes/No
	Condition of the flanking of the road	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/I
b)	Condition of Abutment & Wing walls, Spillway RCC culverts	S/SRI/I
c)	Condition of railings side approach for Bridges	S/SRI/I
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

कामादेश नहीं आया
(LOA निशित
नहीं हुआ है)

Overall Rating :

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Ravi
29/12/2020
(Signature)

NAME: Ravindree Kumar maundal
Junior Engineer