

FIELD INSPECTION REPORT

Date of Inspection: District: Siwam
 Division: Siwam-1 Length (km): 1.200 KM
 Name of the Road: CMDG Road to Saipur
 Scheme/Programme: MAINTENANCE MIR 3054
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Construction/Improvement/Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Shoulder	S
c)	Skidding Index	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
	Construction joints provided or not in CC Pavement	Yes/No
	Compaction of Bank slope & embankments if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Dune pipe culverts including its painting	S/SRI
b)	Condition of Abutment & Wing walls, Slab in R/C culverts	S/SRI
c)	Condition of roadways close approach to Bridges	S/SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Ravi
29/12/2020
25
 (Signature)

NAME: Ravinder Kumar Maishal
Junior Engineer

कार्यालय नरि
 आम्ब
 (L.OA तिथि नदी
 उवाश)