

FIELD INSPECTION REPORT

Date of Inspection: District: Siwan
 Division: Siwan-1 Length (km): 1.700 km
 Name of the Road: PWD Road to Jarenwa
 Scheme/Programme: MAINTENANCE MR 3054
 Package No.: Road Id No.:
 Status of the Project: Original/Completed Under Maintenance
 Work is a case of: New to existing : Regular Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Good functional condition	S/N
b)	Surface of SMC	S/N
c)	Riding Quality	S/N
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided for RCC Pavement	Yes/No
g)	Compaction of flank slope & runoffs if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls on Dune pipe culverts including its painting	S/SRI
b)	Excess water Abutment & Wing walls Stable RCC culverts	S/SRI
c)	Condition of railings sub approach to Bridges	S/SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Ravi
29/12/2020
 (Signature) RE

NAME: Ravindra Kumar mandal
Junior Engineer

कायदेत नमिअम
 (L.O.A बिगि
 नही हवा ई)